





SECOND



TAX 8
0.39± ACRES

LAKE ROAD

GARAGE



FND. 1" PIPE
BEARS S73°38'56"W
2.83' FROM SET
PROPERTY CORNER

EDGE OF LAKE
ROAD AS FIELD
LOCATED

SURVEYOR'S CERTIFICATE

THIS MAP CORRECTLY REPRESENTS A SURVEY MADE BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE REQUIREMENTS OF THE "SURVEY RECORDING ACT" AT THE REQUEST OF CARLA MERRITT.

SECTION 24, TWP 56N, RNG 5W



Surveyor's Signature
SURVEYOR
NON

ON'S

FIRST

ADDITION

T-4 T-3 T-4

ION

AVENUE


10	9	8
5	6	7

12	11	10	9	8	7
16					
1	2	3	4	5	6

T-4	T-3	T-6	T-7
17			
T-5	T-2	T-9	T-8

T-5	T-7	T-6	T-10	
18				
T-2	T-9	T-3	T-8	T-1

T-3	T-2	T-7	T-4
19			
T-1	T-5	T-9	T-10



N

AVENUE

THIRD

SECOND

9	8	7
---	---	---

FIFTH

12	11	10	9	8	7
8					
1	2	3	4	5	6

FOURTH

12	11	10	9	8	7
VACATED					
1	2	3	4	5	6

10	9	8	7	6
6				
1	2	3	4	5


T-5	T-6	T-7	T-1
20			
T-8			
T-2			

4	5	6
---	---	---

RIVER					
-------	--	--	--	--	--

ADDITION					
----------	--	--	--	--	--

1	2	3	4	5
---	---	---	---	---




IT

BLVD.

-5	T-3	T-9	T-5	T-3	W	1/2	10
3							
T-11							

1	2	3	4	5	6
4					



7	8
6	9
5	10
4	11
3	12
2	13
1	14

7	8
6	9
5	10
4	11
3	12
2	13
1	14



[Printer Friendly](#)

Other Maps: **Aerial**



Sentry Dynamics, Inc. 721 Lochsa Suite 16 Post Falls, ID 83854 208.777.1252 www.digitshare.org

Sentry Dynamics, Inc. and its customers make no representations, warranties or conditions, express or implied, as to the accuracy or completeness of information contained in this report.